

**EAST - [golf cart:2]**

**File View Edit Tools Window Help**

**Pending**

**Active**

- L1: (23) ((5,092,512") or ("5,104,026") or ("5,305,625") or ("5,349,521"))
- L2: (0) ((2001/0030432) or (2001/0054827) or (2002/0021937))
- L3: (0) 2001/0030432.pn.
- L4: (1) 20010030432.pn.
- L5: (1) 20010054827.pn.
- L6: (1) 20020021937.pn.
- L7: (1) 20020040525.pn.
- L8: (1) 20020053805.pn.
- L9: (1) 20020060462.pn.
- L10: (10) ((6,042,163") or ("6,174,009") or ("6,179,353"))

**Failed**

- (0) ("296/214.ccls.-296/224.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (0) 11 and (stop adj2 block))
- (0) M.E.D.
- (0) ("200/\$.ccls.").CCLS.
- (0) ("188/\$.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (4) golf near2 cart with solar near2 cells
- (0) 296/110.02.ccls.-296/100.05.ccls.
- (0) ("4662115or4919473or5536060or5924760or5944373or6068327")
- (0) (296/146.5.ccls.).CCLS.
- (0) ((20010030432.pn.") or ("20010054827.pn.") or ("20020060462.pn."))

**Saved**

**Drafts**

**Pending**

**Active**

**Failed**

**Saved**

**Favorites**

**Tagged (7)**

**UDC**

**Queue**

**Trash**

**Search List Browse Queue Clear**

**DBs USPAT**

Highlight all hit terms initially

6,042,163
6,174,009
6,179,353
6,231,095
6,282,769
6,240,820
6,318,775
6,349,521
6,406,077
6,409,239

**Document ID Issue Date Page Title Current**

	U	I	Document ID	Issue Date	Page	Title	Current
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	EP 1356969 A	20031113	12	Cabriolet vehicle comprising a roof with a	
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	EP 949105 A	20030401	6	Vehicle rear luggage compartment with retraction mechanism	
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	EP 1136295 A	20021015	12	Convertible for enabling boot to carry	
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5813594 A	19980929	12	Apparatus for forming an end bumper for vehicle	228/146
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 20010054827	20011227	7	Method for manufacturing a bumper	293/102
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 20020053805	20020509	14	Bumper reinforcement structure	293/102
7	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6240820 B1	20010605	13	Die apparatus for cutting end of bumper bar	83/188

**Hits Details HTML**

Ready

EAST - [golf cart:2]

File View Edit Tools Window Help

Pending  
Active  
L1: (23) ("5,092,512") or ("5,104,026") or ("5,305,625") or  
L2: (0) (2001/0030432) or (2001/0054827) or (2002/0021937)  
L3: (0) 2001/0030432.pn.  
L4: (1) 20010030432.pn.  
L5: (1) 20010054827.pn.  
L6: (1) 20020021937.pn.  
L7: (1) 20020040525.pn.  
L8: (1) 20020053805.pn.  
L9: (1) 20020060462.pn.  
L10: (10) ("6,042,163") or ("6,174,009") or ("6,179,353")  
L11: (624) 293/120-122.ccls.  
L12: (42) 111 and aluminum with steel  
L13: (1) 111 and TRIP  
L14: (0) 111 and Martensic  
L15: (10) 111 and dissimilar  
L16: (38) 111 and thicknesses  
L17: (11) 111 and different near5 thicknesses  
L18: (3) 111 and Martensitic  
L19: (0) trip near5 steel with bumper  
L20: (99) trip near5 steel

Failed  
(0) ("296/214.ccls.-296/224.ccls.").CCLS.  
(0) ("296/\$.ccls.").CCLS.  
(0) ("296/\$.ccls.").CCLS.  
(0) 11 and (stop adj2 block))

Search List Browse Queue Clear  
DBs USPAT Plurals  
Default operator:  Highlight all hit terms initially


trip near5 steel

Drafts

Pending  
Active  
Failed  
Saved  
Favorites  
Tagged (17)  
UDC  
Queue  
Trash

	U	I	Document ID	Issue Dat	Page	Title	Curre
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5813594 A	19980929	12	Apparatus for forming an end bumper for vehicle	228/14
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 20010054827	20011227	7	Method for manufacturing a bumper	293/10
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 20020053805	20020509	14	Bumper reinforcement structure	293/10
7	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6240820 B1	20010605	13	Die apparatus for cutting end of bumper b	83/188
8	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6406081 B1	20020618	10	Energy absorber system	293/13
9	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6308999 B1	20011030	8	Multi-material hybrid bumper	293/10
10	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4569865 A	19860211	8	Bumper fascia and process to bond ionomer	428/31
11	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3779592 A	19731218	4	HIGH STRENGTH VEHICLE BUMPER	293/12
12	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5154462 A	19921013	8	Method for making a bonded vehicular cross	293/12
13	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6685243 B1	20040203	10	Bumper for reducing pedestrian injury	293/10
14	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6371540 B1	20020416	11	Bumper beam for motor vehicles	293/10
15	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6000738 A	19991214	7	Force-absorbing vehicle bumper	293/10
16	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4221413 A	19800909	8	Shock absorption bumper for an automotive vehicle	293/12
17	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5799991 A	19980901	6	Molded bumper system with reinforcement beam	293/12

Hits Details HTML



Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Err
8	BRS	L8	1	20020053805.pn.	US-P GPUB	2004/02/2 0 06:15	
9	BRS	L9	1	20020060462.pn.	US-P GPUB	2004/02/2 0 06:17	
10	IS&R	L10	10	(("6,042,163") or ("6,174,009") or ("6,	USPA T	2004/02/2 0 06:24	
11	BRS	L11	624	293/120-122.ccis.	USPA T	2004/02/2 0 06:25	
12	BRS	L12	42	111 and aluminum with steel	USPA T	2004/02/2 0 06:34	
13	BRS	L13	1	111 and TRIP	USPA T	2004/02/2 0 06:35	
14	BRS	L14	0	111 and Martensic	USPA T	2004/02/2 0 06:35	
15	BRS	L15	10	111 and dissimilar	USPA T	2004/02/2 0 06:41	
16	BRS	L16	38	111 and thicknesses	USPA T	2004/02/2 0 06:54	
17	BRS	L17	11	111 and different near5 thicknesses	USPA T	2004/02/2 0 06:59	
18	BRS	L18	3	111 and Martensitic	USPA T	2004/02/2 0 07:00	
19	BRS	L19	0	trip near5 steel with bumper	USPA T	2004/02/2 0 07:00	
20	BRS	L20	99	trip near5 steel	USPA T	2004/02/2 0 07:00	

Ready

EAST - [golf cart:2]

File View Edit Tools Window Help

Pending Active

L1: (23) (("5,092,512") or ("5,104,026") or ("5,305,625") or ("5,306,058") or ("5,340,177") or (...) L2: (0) ((2001/0030432) or (2001/0054827) or (2002/0021937) L3: (0) 2001/0030432.pn. L4: (1) 20010030432.pn. L5: (1) 20010054827.pn. L6: (1) 20020021937.pn. L7: (1) 20020040525.pn. L8: (1) 20020053805.pn. L9: (1) 20020060462.pn. L10: (10) (("6,042,163") or ("6,174,009") or ("6,179,353")) L11: (624) 293/120-122.ccls. L12: (42) l11 and aluminum with steel L13: (1) l11 and TRIP L14: (0) l11 and Martensic L15: (10) l11 and dissimilar

Failed

(0) ("296/214.ccls.-296/224.ccls.").CCLS. (0) ("296/\$.ccls.").CCLS. (0) ("296/\$.ccls.").CCLS. (0) l1 and (stop adj2 block) (0) M.E.D. (0) ("200/\$.ccls.").CCLS. (0) ("188/\$.ccls.").CCLS. (0) ("296/\$.ccls.").CCLS. (4) golf near2 cart with solar near2 cell\$

Default operator:  Highlight all hit terms initially

111 and dissimilar

Drafts

Pending Active

Failed Saved Favorites Tagged (12) UDC Queue Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Err
3	BRS	L3	0	2001/0030432.pn.	US-P GPUB	2004/02/2 0 06:11		
4	BRS	L4	1	20010030432.pn.	US-P GPUB	2004/02/2 0 06:12		
5	BRS	L5	1	20010054827.pn.	US-P GPUB	2004/02/2 0 06:12		
6	BRS	L6	1	20020021937.pn.	US-P GPUB	2004/02/2 0 06:13		
7	BRS	L7	1	20020040525.pn.	US-P GPUB	2004/02/2 0 06:14		
8	BRS	L8	1	20020053805.pn.	US-P GPUB	2004/02/2 0 06:15		
9	BRS	L9	1	20020060462.pn.	US-P GPUB	2004/02/2 0 06:17		
10	IS&R	L10	10	(("6,042,163") or ("6,174,009") or ("6,179,353"))	USPA T	2004/02/2 0 06:24		
11	BRS	L11	624	293/120-122.ccls.	USPA T	2004/02/2 0 06:25		
12	BRS	L12	42	l11 and aluminum with steel	USPA T	2004/02/2 0 06:34		
13	BRS	L13	1	l11 and TRIP	USPA T	2004/02/2 0 06:35		
14	BRS	L14	0	l11 and Martensic	USPA T	2004/02/2 0 06:35		
15	BRS	L15	10	l11 and dissimilar	USPA T	2004/02/2 0 06:35		

Hits Details HTML

EAST - [golf cart:2]

File View Edit Tools Window Help

Pending  
Active  
L1: (23) ("5,092,512") or ("5,104,026") or ("5,305,625") or  
L2: (0) ((2001/0030432) or (2001/0054827) or (2002/0021937)  
L3: (0) 2001/0030432.pn.  
L4: (1) 20010030432.pn.  
L5: (1) 20010054827.pn.  
L6: (1) 20020021937.pn.  
L7: (1) 20020040525.pn.  
L8: (1) 20020053805.pn.  
L9: (1) 20020060462.pn.  
L10: (10) ("6,042,163") or ("6,174,009") or ("6,179,353")  
L11: (624) 293/120-122.ccls.  
L12: (42) 111 and aluminum with steel  
L13: (1) 111 and TRIP  
L14: (0) 111 and Martensic  
L15: (10) 111 and dissimilar

Failed  
(0) ("296/214.ccls.-296/224.ccls.").CCLS.  
(0) ("296/\$.ccls.").CCLS.  
(0) ("296/\$.ccls.").CCLS.  
(0) 11 and (stop adj2 block)  
(0) M.E.D.  
(0) ("200/\$.ccls.").CCLS.  
(0) ("188/\$.ccls.").CCLS.  
(0) ("296/\$.ccls.").CCLS.  
(4) golf near2 cart with solar near2 cell\$

Search List Browse Queue Clear  
DBs USPAT Plurals  
Default operator:  Highlight all hit terms initially

111 and dissimilar

Drafts  
Pending  
Active  
Failed  
Saved  
Favorites  
Tagged (12)  
UDC  
Queue  
Trash

	U	I	Document ID	Issue Dat	Page	Title	Current
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	EP 1356969 A	20031113	12	Cabriolet vehicle comprises a roof with a	
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	EP 949105 A	20030401	6	Vehicle rear luggage compartment with retrac	
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	EP 1136295 A	20021015	12	Convertible for enabling boot to carry	
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5813594 A	19980929	12	Apparatus for forming an end bumper for vehic	228/146
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 20010054827	20011227	7	Method for manufacturing a bumper	293/102
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 20020053805	20020509	14	Bumper reinforcement structure	293/102
7	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6240820 B1	20010605	13	Die apparatus for cutting end of bumper b	83/188
8	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6406081 B1	20020618	10	Energy absorber system	293/133
9	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6308999 B1	20011030	8	Multi-material hybrid bumper	293/109
10	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4569865 A	19860211	8	Bumper fascia and process to bond ionomer	428/31
11	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3779592 A	19731218	4	HIGH STRENGTH VEHICLE BUMPER	293/120
12	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5154462 A	19921013	8	Method for making a bonded vehicular cross	293/120

Hits Details HTML

EAST - [golf cart:2]

File View Edit Tools Window Help

Pending

Active

- L1: (23) ((5,092,512") or ("5,104,026") or ("5,305,625") or ("5,349,521") or ("6,042,163") or ("6,174,009") or ("6,179,353") or ("6,231,095") or ("6,282,769") or ("6,240,820") or ("6,318,775") or ("6,349,521") or ("6,406,077") or ("6,409,239"))
- L2: (0) ((2001/0030432) or (2001/0054827) or (2002/0021937))
- L3: (0) 2001/0030432.pn.
- L4: (1) 20010030432.pn.
- L5: (1) 20010054827.pn.
- L6: (1) 20020021937.pn.
- L7: (1) 20020040525.pn.
- L8: (1) 20020053805.pn.
- L9: (1) 20020060462.pn.
- L10: (10) ((6,042,163") or ("6,174,009") or ("6,179,353"))

Failed

- (0) ("296/214.ccls.-296/224.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (0) 11 and (stop adj2 block))
- (0) M.E.D.
- (0) ("200/\$.ccls.").CCLS.
- (0) ("188/\$.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (4) golf near2 cart with solar near2 cell\$
- (0) 296/110.02.ccls.-296/100.05.ccls.
- (0) ("4662115or4919473or5536060or5924760or5944373or6068327")
- (0) (296/146.5.ccls.).CCLS.
- (0) ((20010030432.pn.") or ("20010054827.pn.") or ("20020021937.pn."))

Saved

Search List Browse Queue Clear

DBs USPAT

Highlight all hit terms initially

6,042,163
6,174,009
6,179,353
6,231,095
6,282,769
6,240,820
6,318,775
6,349,521
6,406,077
6,409,239

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (7)

UDC

Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
1	IS&R	L1	23	((5,092,512") or ("5,104,026") or ("5,305,625") or ("5,349,521") or ("6,042,163") or ("6,174,009") or ("6,179,353") or ("6,231,095") or ("6,282,769") or ("6,240,820") or ("6,318,775") or ("6,349,521") or ("6,406,077") or ("6,409,239"))	USPA	2004/02/2 T 0 06:08		
2	IS&R	L2	0	((2001/0030432) or (2001/0054827) or (2002/0021937))	US-P	2004/02/2 GPUB 0 06:08		
3	BRS	L3	0	2001/0030432.pn.	US-P	2004/02/2 GPUB 0 06:11		
4	BRS	L4	1	20010030432.pn.	US-P	2004/02/2 GPUB 0 06:12		
5	BRS	L5	1	20010054827.pn.	US-P	2004/02/2 GPUB 0 06:12		
6	BRS	L6	1	20020021937.pn.	US-P	2004/02/2 GPUB 0 06:13		
7	BRS	L7	1	20020040525.pn.	US-P	2004/02/2 GPUB 0 06:14		
8	BRS	L8	1	20020053805.pn.	US-P	2004/02/2 GPUB 0 06:15		
9	BRS	L9	1	20020060462.pn.	US-P	2004/02/2 GPUB 0 06:17		
10	IS&R	L10	10	((6,042,163") or ("6,174,009") or ("6,179,353"))	USPA	2004/02/2 T 0 06:17		

Hits Details HTML

Ready NUM